

1 03JUN22

_UNIT 166 EDI 32MI EL MONTE CA X at POMONA CA

2022/06/06 11:12:00

E	ORL		1050A	*SUSPENDED*	DP *SUSPENDED*
E	6 WPK		1108A	*SUSPENDED*	
E	XSF		1133A	*SUSPENDED*	
E	77 DLD		1156A	*SUSPENDED*	
E	68 PAK		1242P	*SUSPENDED*	
E	XPX		1251P	*SUSPENDED*	
E	114 JAX	0220P	0235P	*SUSPENDED*	
E	1 JAX	0220P	0235P	*SUSPENDED*	
E	XB1		0256P	*SUSPENDED*	
E	66 LEC		0338P	*SUSPENDED*	
E	51 MDO		0428P	*SUSPENDED*	
E	XDF		0500P	*SUSPENDED*	
E	54 TLH		0552P	*SUSPENDED*	
C	87 CIP		0658P	*SUSPENDED*	
C	66 CSV		0825P	*SUSPENDED*	
C	63 PNS	0942P	0957P	*SUSPENDED*	
C	XFM		1057P	*SUSPENDED*	
C	59 ATR		1127P	*SUSPENDED*	
C	XTC		1213A	*SUSPENDED*	
C	44 MOE		1234A	*SUSPENDED*	
C	40 PAG		0116A	*SUSPENDED*	
C	X1G		0126A	*SUSPENDED*	
C	21 BIX		0141A	*SUSPENDED*	
C	12 GUF		0200A	*SUSPENDED*	
C	15 BAS		0223A	*SUSPENDED*	
C	XL4		0248A	*SUSPENDED*	
C	XNO		0551A	*SUSPENDED*	
C	XEJ		0600A	*SUSPENDED*	
C	76 NOL		0900A	(CHCC/NTMS)	AR 0920A DP 0920A 20 MI LATE
		RMK:...	(3360 04JUN22) PTC ISSUE		
C	XN7		0906A	(CHCC/CHCC)	AR 0933A DP 0933A 27 MI LATE
C	XSU		0915A	(NTMS/NTMS)	AR 0946A DP 0946A 31 MI LATE
C	XEB		0920A	(eDr (00823003)/eDr (00823003))	AR 1048A DP 1048A 1 HR 28 MI LATE
C	XWB		0940A	(eDr (00823003)/eDr (00823003))	AR 1107A DP 1107A 1 HR 27 MI LATE
C	XLL		0954A	(eDr (00823003)/eDr (00823003))	AR 1145A DP 1145A 1 HR 51 MI LATE
C	56 SCH		1030A	(NTMS/NTMS)	AR 1231P DP 1236P 2 HR 6 MI LATE
		RMK:...	(3360 04JUN22) FREIGHT INTERFERENCE		
C	72 NIB		1156A	(NTMS/NTMS)	AR 0207P DP 0209P 2 HR 13 MI LATE
C	18 LFT		1224P	(NTMS/NTMS)	AR 0233P DP 0238P 2 HR 14 MI LATE
C	XIJ		0143P	(UPRR/UPRR)	AR 0407P DP 0407P 2 HR 24 MI LATE
C	74 LCH		0155P	(NTMS/NTMS)	AR 0420P DP 0421P 2 HR 26 MI LATE
C	XFC		0245P	*DEPARTED*	
C	60 BMT	0334P	0348P	(NTMS/NTMS)	AR 0544P DP 0555P 2 HR 7 MI LATE
C	XCB		0448P	*DEPARTED*	
C	82 HOS	0618P	0655P	(NTMS/NTMS)	AR 0808P DP 0830P 1 HR 35 MI LATE
C	XWJ		0720P	(UPRR/UPRR)	AR 0856P DP 0856P 1 HR 36 MI LATE
C	XRБ		0746P	(UPRR/UPRR)	AR 1033P DP 1033P 2 HR 47 MI LATE

			RMK:...	(1759 04JUN22) HARLEM, MWARNK-07 KCS 4703. ACTUATED HI-WIDE DETECTOR
C		XEA	0816P	(eDr (00806547)/eDr (00806547)) AR 1127P DP 1127P 3 HR 11 MI LATE
C		XFA	0906P	(UPRR/UPRR) AR 1225A DP 1225A 3 HR 19 MI LATE
C		XKG	0951P	(UPRR/UPRR) AR 0219A DP 0219A 4 HR 28 MI LATE
C		XKY	1115P 1123P	(eDr (00806547)/eDr (00806547)) AR 0259A DP 0305A 3 HR 42 MI LATE
C	215	SAS	1205A 0245A	(1759/NTMS) AR 0326A DP 0502A 2 HR 17 MI LATE
			RMK:...	(3360 04JUN22) CNDR ONLY SAS-ALP
C		XHT	0354A	(UPRR/UPRR) AR 0739A DP 0739A 3 HR 45 MI LATE
C		XPF	0508A	(UPRR/UPRR) AR 0914A DP 0914A 4 HR 6 MI LATE
C	169	DRT	0549A	(NTMS/NTMS) AR 0952A DP 1004A 4 HR 15 MI LATE
			RMK:...	(7092 05JUN22) DELAYED W/SAS DUE TO UP FREIGHT IN UDE A/H
C		XLY	0659A	(UPRR/UPRR) AR 1116A DP 1116A 4 HR 17 MI LATE
C		XAW	0740A	*DEPARTED*
C	124	SND	0824A	(NTMS/NTMS) AR 1241P DP 1241P 4 HR 17 MI LATE
C		XMZ	0926A	*DEPARTED*
C	95	ALP	1028A 1038A	(NTMS/NTMS) AR 0341P DP 0401P 5 HR 23 MI LATE
			RMK:...	(7092 05JUN22) DELAYED E/ALP WAITING ON RECREW
C		XVL	1138A	(UPRR/UPRR) AR 0628P DP 0628P 6 HR 50 MI LATE
C		XTS	1233P	(eDr (00035722)/eDr (00035722)) AR 0733P DP 0733P 7 HR LATE
C		XMQ	1258P	*DEPARTED*
C		XTT	0118P	*DEPARTED*
M	219	ELP	0122P 0147P	(NTMS/NTMS) AR 0841P DP 0905P 7 HR 18 MI LATE
			RMK:...	(1759 05JUN22) MARFA, MEET UP6739
M		XLN	0222P	*DEPARTED*
			RMK:...	(6315 05JUN22) ELP-MRC CND THOMPSON 267-667-1290 A/C SPENCER TUS 20+ BAGS IN COACHBAG
M	86	DEM	0318P	(eDr (00819010)/eDr (00819010)) AR 1037P DP 1038P 7 HR 20 MI LATE
M	60	LDB	0413P	(NTMS/NTMS) AR 1133P DP 1142P 7 HR 29 MI LATE
M		XLZ	0416P	*DEPARTED*
M	117	BEN	0518P	(NTMS/NTMS) AR 1235A DP 1240A 7 HR 22 MI LATE
M	47	TUS	0645P 0735P	(NTMS/NTMS) AR 0142A DP 0226A 6 HR 51 MI LATE
M		XRE	0758P	*DEPARTED*
M		XCG	0831P	*DEPARTED*
M	85	MRC	0852P 0902P	(NTMS/NTMS) AR 0337A DP 0354A 6 HR 52 MI LATE
M		XZS	0955P	(eDr (00088366)/eDr (00088366)) AR 0455A DP 0455A 7 HR LATE
M		XWZ	1048P	*DEPARTED*
M	165	YUM	1149P	(NTMS/NTMS) AR 0639A DP 0648A 6 HR 59 MI LATE
P		XIC	1240A	(UPRR/UPRR) AR 0739A DP 0739A 6 HR 59 MI LATE
P		XTH	0124A	(UPRR/UPRR) AR 0825A DP 0825A 7 HR 1 MI LATE
P	151	PSN	0202A	(eDr (00088366)/eDr (00088366)) AR 0852A DP 0852A 6 HR 50 MI LATE
P		XBZ	0227A	*DEPARTED*
P	62	ONA	0354A	(NTMS/NTMS) AR 1038A DP 1042A 6 HR 48 MI LATE
P	8	POS	0404A	(NTMS/NTMS) AR 1050A DP 1051A 6 HR 47 MI LATE
P		XEL	0505A	(UPRR/UPRR) AR 1112A DP 1112A 6 HR 7 MI LATE
P	30	LAX	0535A	(NTMS/) AR 1138A 6 HR 3 MI LATE

NOL-BMT Conductor=00823003

00823003	0 SED	NOL-NOL	SYS	020 AM	PTC problem or failure (cause unknown) PTC screen would not allow engineers to initialize., Other, naupt
00823003	1 SED	NOL-XSU	DCS	010 AM	Restrictive signal(s) from unknown cause Stop, Control Point, Carrollton
00823003	2 SED	NOL-XSU	DCS	006 CC	Restrictive signal(s) from unknown cause Stop, Control Point, Southport

00823003	3 SED	XSU-XEB	DCS	024 UP	Restrictive signal(s) from known wayside signal failure CC dispatcher said our request is in for the UP to accept us; however, UP said request is not in his system., Stop, Control Point, East Bridge JCT
00823003	4 SED	XSU-XEB	FTI	030 CC	Cross Traffic Control Point, East Bridge JCT, Unknown
00823003	5 SED	XSU-XEB	DSR	003 CC	Per bulletin Milepost, 908.73, 908.5, 10, Main, Milepost, 908.5, 906.4, 25, Main
00823003	6 SED	XWB-XLL	FTI	031 BN	Meet Other, Avondale BN Yard, Freight train on BN main; our route 2-B, 108 track, BN 5838 E
00823003	7 SED	XLL-SCH	DSR	009 BN	Per bulletin Milepost, 16.9, 17.0, 25, Main, Milepost, 21.1, 21.3, 40, Main, Milepost, 31.8, 32.0, 50, Main, Milepost, 35.6, 35.7, 50, Main, Milepost, 38.5, 39.5, 55, Main, Milepost, 49.5, 51.2, 50, Main, Milepost, 54.0, 54.2, 25, Main
00823003	8 SED	SCH-SCH	ADA	003 BN	Mobility Impaired
00823003	9 SED	SCH-NIB	DSR	007 BN	Per dispatcher (radio/phone) Milepost, 88.6, 88.8, 10, Main, Milepost, 118.2, 118.6, 30, Main, Milepost, 121.7, 122.1, 30, Main
00823003	10 SED	SCH-NIB	DSR	002 BN	Per bulletin Milepost, 55.2, 68.5, 50, Main, Milepost, 69.9, 70.0, 40, Main, Milepost, 70.8, 71.0, 50, Main, Milepost, 81.5, 81.8, 30, Main
00823003	11 SED	NIB-LFT	SYS	002 BN	Delay in Block
00823003	12 SED	LFT-LFT	ADA	002 BN	Mobility Impaired
00823003	13 SED	LFT-XIJ	DCS	003 BN	Restrictive signal(s) from unknown cause Approach, Stop, Milepost w/Letters, E Lacassine, Lacassine
00823003	14 SED	LFT-XIJ	DSR	001 BN	Per bulletin Milepost, 156.0, 157.2, 50, Main
00823003	15 SED	LFT-XIJ	RTE	010 BN	Line manual or spring switch Siding, WSS Roanoke
00823003	16 SED	LFT-XIJ	SYS	005 BN	Delay in Block
00823003	17 SED	LCH-BMT	FTI	004 UP	Meet BN 8131 E, Siding, Echo
00823003	18 SED	LCH-BMT	DSR	000 UP	Per bulletin Milepost, 220.1, 220.25, 30, Main

BMT-SAS Conductor=00806547

00806547	19 SWD	BMT-HOS	DSR	005 UP	Per bulletin Milepost, 322, 322.1, 30, ., Milepost, 343.1, 343.5, 30, ., Milepost, 346.15, 346.25, 20, ., Milepost, 354.25, 356.2, 25, 1
00806547	20 SWD	BMT-HOS	FTI	003 UP	Meet up8721w, Siding, dayton
00806547	21 SWD	BMT-HOS	FTI	015 UP	Meet Take siding, first signal was a restricting then approach, up6980w, Siding, hatchery/fauna
00806547	22 SWD	BMT-HOS	FTI	006 UP	Follow kcs4703w, Milepost, 348, 361
00806547	23 SWD	HOS-XWJ	DSR	001 UP	Per bulletin Milepost, 376.35, 376.85, 30, 2
00806547	24 SWD	XWJ-XRB	FTI	071 UP	Follow Freight train ahead had to stop and inspect BC of a high wide detector, we stop at mp30 waiting, kcs4703w, Milepost, 16, 36
00806547	25 SWD	XRB-XEA	DSR	002 UP	Per bulletin Milepost, 36.25, 36.35, 30, ., Milepost, 51.95, 52.1, 40, .
00806547	26 SWD	XRB-XEA	FTI	022 UP	Meet up6455e, Siding, eagle lake
00806547	27 SWD	XEA-XFA	DSR	002 UP	Per bulletin Milepost, 74.85, 75, 60, ., Milepost, 78.70, 79.2, 60, ., Milepost, 83.2, 83.4, 60, ., Milepost, 84, 84.1, 60, ., Milepost, 105.25, 105.85, 60, ., Milepost, 109.75, 110, 60, ., Milepost, 111.25, 111.75, 45, ., Milepost, 116.65, 116.8, 60, .
00806547	28 SWD	XEA-XFA	FTI	006 UP	Meet up5747e, Siding, glidden
00806547	29 SWD	XFA-XKG	FTI	069 UP	Follow Up 7918w went into emergency at Luling, had to walk train and then the dispatcher moved the up8845w up to Kingsbury and we followed them next, up7918w, up8845w, Milepost, 138.1, 160.1
00806547	30 SWD	XKG-XKY	DSR	000 UP	Per bulletin Milepost, 174.4, 174.5, 55, ., Milepost, 178.5, 178.65, 60, ., Milepost, 187.05, 187.15, 60, ., Milepost, 197.55, 197.85, 60, 2
00806547	31 SWD	XKY-SAS	SVS	004 UP	Normal switch / set out / pick up of locomotives, cars or section of train Had to go to west end of SAS depo and back into station to add 421 transfer cars, Milepost, 209.7, 209.4

SAS-ALP Conductor=00817950

00817950	32 SWD	SAS-XHT	FTI	005 UP	Meet UP6625, Siding, Dunlay
00817950	33 SWD	SAS-XHT	FTI	079 UP	Follow Stopped behind broke down freight at Enterprise, UP8637, Milepost, 249, 260
00817950	34 SWD	SAS-XHT	DSR	002 UP	Per bulletin Milepost, 221.75, 222.25, 25, MT, Milepost, 223.55, 223.65, 40, MT, Milepost, 243.6, 244.1, 45, MT, Milepost, 247.0, 247.25, 55, MT
00817950	35 SWD	SAS-XHT	FTI	011 UP	Meet Control Point, SA214, UP4873
00817950	36 SWD	XHT-XPf	DSR	001 UP	Per bulletin Milepost, 321.55, 322.95, 45, MT
00817950	37 SWD	XHT-XPf	PTI	001 UP	Meet Amtrak 2, Siding, Obi
00817950	38 SWD	XHT-XPf	FTI	011 UP	Follow UP8637, Milepost 260, 284

00817950	39 SWD	XHT-XPX	DSR	008	UP	Per bulletin Milepost, 263.5, 263.75, 60, MT, Milepost, 270.4, 270.6, 60, MT, Milepost, 277.0, 277.25, 70, MT, Milepost, 277.65, 277.85, 75, MT, Milepost, 291.0, 291.15, 70, MT
00817950	40 SWD	XPX-DRT	OTH	003	UP	Lost time - N.A.R. Insufficient runtime
00817950	41 SWD	DRT-DRT	HLD	010	UP	Passenger and/or baggage Single conductor, multiple doors, and picked up Union Pacific pilots
00817950	42 SWD	DRT-XLY	OTH	005	UP	Lost time - N.A.R. Insufficient runtime
00817950	43 SWD	XLY-SND	DSR	001	UP	Per bulletin Milepost, 475.7, 476.1, 30, MT
00817950	44 SWD	XLY-SND	FTI	004	UP	Meet UP6315, Siding, Malvado
00817950	45 SWD	XLY-SND	DSR	002	UP	Per bulletin Milepost, 461.65, 461.75, 25, MT
00817950	46 SWD	SND-ALP	DCS	018	UP	Restrictive signal(s) from unknown cause Stop, Control Point, SA269
00817950	47 SWD	SND-ALP	DSR	001	UP	Per dispatcher (radio/phone) Milepost, 523.6, 523.9, 45, MT
00817950	48 SWD	SND-ALP	SYS	044	UP	Re-crew / job briefing Siding, Warwick
00817950	49 SWD	SND-ALP	DSR	003	UP	Per bulletin Milepost, 527.20, 527.30, 50, MT, Milepost, 531.75, 532.0, 30, MT, Milepost, 545.7, 545.8, 50, MT
00817950	50 SWD	SND-ALP	SVS	013	UP	Initializing PTC (no failure) Siding, Warwick
00817950	51 SWD	SND-ALP	DSR	003	UP	Per bulletin Milepost, 591.7, 592.5, 45, MT, Milepost, 592.5, 592.9, 25, MT
00035722	52 SWD	ALP-ALP	HLD	010	UP	Passenger and/or baggage
00035722	53 SWD	ALP-XVL	FTI	007	UP	Cross over or go around UP6365, Control Point, AARGON
00035722	54 SWD	ALP-XVL	FTI	080	UP	Meet Up inbound crew wait for relief crew @ mp647.9 mt, Up6739, Control Point, Marfa
00035722	55 SWD	XVL-XTS	DSR	005	UP	Per bulletin Milepost, 740.10, 740.70, 25, mt
00035722	56 SWD	XVL-XTS	SYS	005	UP	PTC-caused slow-down or penalty stop Air brake penalty up suppression. Fault 2455 IFC, Milepost, 688, 688
00035722	57 SWD	XTS-ELP	FTI	032	UP	Blocked from station track Siding, Amtrak, Up7463
00035722	58 SWD	XTS-ELP	INJ	005	UP	Injured or sick passenger

ELP-MRC Conductor=00819010

00819010	59 SWD	ELP-DEM	FTI	010	UP	Meet up8754, Milepost, 1287, 1289
00819010	60 SWD	DEM-LDB	FTI	007	UP	Meet up8957, Milepost, 1171, 1172
00819010	61 SWD	LDB-LDB	HLD	007	UP	Multiple spots Spot the 0130, 15, and 2130 cars
00819010	62 SWD	BEN-BEN	HLD	003	UP	High passenger count 14 pax in car 5,6,7
00819010	63 SWD	BEN-TUS	FTI	009	UP	Meet up7051, Milepost, 1036, 1036

MRC-LAX Conductor=00088366

00088366	64 SWD	MRC-MRC	ADA	003	UP	Mobility Impaired
00088366	65 SWD	MRC-MRC	HLD	002	UP	Multiple spots
00088366	66 SWD	MRC-MRC	SYS	002	UP	Re-crew / job briefing Other, Maricopa Station
00088366	68 SWD	MRC-XZS	FTI	005	UP	Meet up, Milepost, 846.9, 845.2
00088366	69 SWD	MRC-XZS	DCS	003	UP	Initialize PTC restricted speed to signal Milepost, 897.8, 897
00088366	70 SWD	XZS-YUM	FTI	010	UP	Meet up 5889, Milepost, 784.8, 783.1
00088366	67 SWD	YUM-YUM	ADA	005	UP	Mobility Impaired
00088366	71 SWD	YUM-XIC	RTE	003	UP	Crossover Milepost, 714.9, 697.1
00088366	72 SWD	XIC-XTH	RTE	002	UP	Crossover Milepost, 637.1, 637.1
00088366	73 SWD	PSN-ONA	FTI	018	UP	Meet up 7874, Milepost, 538.5, 534.7
00088366	74 SWD	PSN-ONA	DSR	003	UP	Per bulletin Milepost, 537.90, 537.80, 10, 2, Milepost, 532.5, 532, 40, 1
00088366	75 SWD	POS-XEL	OTH	002	UP	Lost time - N.A.R.
00088366	76 SWD	XEL-LAX	RTE	007	SC	Crossover from the UP to Metrolink Milepost, 482.8, 1.3