

1 02SEP22

_UNIT 163 EDI 32MI EL MONTE CA X at POMONA CA

2022/09/05 09:39:00

E		ORL		1050A	*SUSPENDED*	DP *SUSPENDED*
E	6	WPK		1108A	*SUSPENDED*	
E		XSF		1133A	*SUSPENDED*	
E	77	DLD		1156A	*SUSPENDED*	
E	68	PAK		1242P	*SUSPENDED*	
E		XPX		1251P	*SUSPENDED*	
E	114	JAX	0220P	0235P	*SUSPENDED*	
E	1	JAX	0220P	0235P	*SUSPENDED*	
E		XB1		0256P	*SUSPENDED*	
E	66	LEC		0338P	*SUSPENDED*	
E	51	MDO		0428P	*SUSPENDED*	
E		XDF		0500P	*SUSPENDED*	
E	54	TLH		0552P	*SUSPENDED*	
C	87	CIP		0658P	*SUSPENDED*	
C	66	CSV		0825P	*SUSPENDED*	
C	63	PNS	0942P	0957P	*SUSPENDED*	
C		XFM		1057P	*SUSPENDED*	
C	59	ATR		1127P	*SUSPENDED*	
C		XTC		1213A	*SUSPENDED*	
C	44	MOE		1234A	*SUSPENDED*	
C	40	PAG		0116A	*SUSPENDED*	
C		X1G		0126A	*SUSPENDED*	
C	21	BIX		0141A	*SUSPENDED*	
C	12	GUF		0200A	*SUSPENDED*	
C	15	BAS		0223A	*SUSPENDED*	
C		XL4		0248A	*SUSPENDED*	
C		XNO		0551A	*SUSPENDED*	
C		XEJ		0600A	*SUSPENDED*	
C	76	NOL		0900A	(CHCC/NTMS)	AR 0900A DP 0900A ON TIME
C		XN7		0906A	(CHCC/CHCC)	AR 0907A DP 0907A 1 MI LATE
C		XSU		0915A	(NTMS/NTMS)	AR 0911A DP 0911A 4 MI EARLY
C		XEB		0920A	(eDr (landje)/eDr (landje))	AR 0936A DP 0936A 16 MI LATE
C		XWB		0940A	(eDr (landje)/eDr (landje))	AR 0955A DP 0955A 15 MI LATE
C		XLL		0954A	(eDr (landje)/eDr (landje))	AR 1020A DP 1020A 26 MI LATE
C	56	SCH		1030A	(NTMS/NTMS)	AR 1104A DP 1106A 36 MI LATE
C	72	NIB		1156A	(NTMS/NTMS)	AR 1242P DP 1245P 49 MI LATE
C	18	LFT		1224P	(NTMS/NTMS)	AR 0109P DP 0112P 48 MI LATE
C		XIJ		0143P	(UPRR/UPRR)	AR 0222P DP 0222P 39 MI LATE
C	74	LCH		0155P	(NTMS/NTMS)	AR 0235P DP 0238P 43 MI LATE
C		XFC		0245P	*DEPARTED*	
C	60	BMT	0334P	0348P	(NTMS/NTMS)	AR 0351P DP 0404P 16 MI LATE
C		XCB		0448P	*DEPARTED*	
C	82	HOS	0618P	0655P	(NTMS/NTMS)	AR 0711P DP 0734P 39 MI LATE
		RMK:...		(3360 03SEP22) WEATHER DELAYS - SIGNALS/FTI		
C		XWJ		0720P	(UPRR/UPRR)	AR 0901P DP 0901P 1 HR 41 MI LATE
C		XRFB		0746P	(UPRR/UPRR)	AR 0956P DP 0956P 2 HR 10 MI LATE
C		XEA		0816P	(UPRR/UPRR)	AR 1034P DP 1034P 2 HR 18 MI LATE
C		XFA		0906P	(UPRR/UPRR)	AR 1252A DP 1252A 3 HR 46 MI LATE

C		XKG		0951P	(UPRR/UPRR)	AR 0135A DP 0135A 3 HR 44 MI LATE
C		XKY	1115P	1123P	(eDr (00019458)/eDr (00019458))	AR 0216A DP 0228A 3 HR 5 MI LATE
C	215	SAS	1205A	0245A	(eDr (00019458)/NTMS)	AR 0244A DP 0418A 1 HR 33 MI LATE
C		XHT		0354A	(UPRR/UPRR)	AR 0536A DP 0536A 1 HR 42 MI LATE
C		XPF		0508A	(UPRR/UPRR)	AR 0739A DP 0739A 2 HR 31 MI LATE
C	169	DRT		0549A	(NTMS/NTMS)	AR 0820A DP 0821A 2 HR 32 MI LATE
			RMK:...	(7490 04SEP22) FOLLOW ISASI-04 FEELY/MP404 TO DRYDEN/MP482		
C		XLY		0659A	(UPRR/UPRR)	AR 1117A DP 1117A 4 HR 18 MI LATE
C		XAW		0740A	*DEPARTED*	
C	124	SND		0824A	(NTMS/NTMS)	AR 0134P DP 0135P 5 HR 11 MI LATE
C		XMZ		0926A	*DEPARTED*	
C	95	ALP	1028A	1038A	(NTMS/NTMS)	AR 0355P DP 0413P 5 HR 35 MI LATE
			RMK:...	(7490 06SEP22) .		
C		XVL		1138A	(eDr (00035722)/eDr (00035722))	AR 0513P DP 0513P 5 HR 35 MI LATE
C		XTS		1233P	(eDr (00035722)/eDr (00035722))	AR 0614P DP 0614P 5 HR 41 MI LATE
C		XMZ		1258P	*DEPARTED*	
C		XTT		0118P	*DEPARTED*	
M	219	ELP	0122P	0147P	(NTMS/NTMS)	AR 0649P DP 0711P 5 HR 24 MI LATE
			RMK:...	(6315 04SEP22) ELP-MRC CND ONTIVEROS 267-667-1155A/C SPENCER 267-667-1133 TUS = 20 PCS		
M		XLN		0222P	*DEPARTED*	
M	86	DEM		0318P	(NTMS/NTMS)	AR 0859P DP 0900P 5 HR 42 MI LATE
M	60	LDB		0413P	(NTMS/NTMS)	AR 0950P DP 0950P 5 HR 37 MI LATE
M		XLZ		0416P	*DEPARTED*	
M	117	BEN		0518P	(eDr (00812091)/eDr (00812091))	AR 1045P DP 1046P 5 HR 28 MI LATE
M	47	TUS	0645P	0735P	(NTMS/NTMS)	AR 1149P DP 1226A 4 HR 51 MI LATE
M		XRE		0758P	*DEPARTED*	
M		XCG		0831P	*DEPARTED*	
M	85	MRC	0852P	0902P	(NTMS/NTMS)	AR 0144A DP 0214A 5 HR 12 MI LATE
M		XZS		0955P	(eDr (00086817)/eDr (00086817))	AR 0328A DP 0328A 5 HR 33 MI LATE
M		XWZ		1048P	*DEPARTED*	
M	165	YUM		1149P	(NTMS/NTMS)	AR 0504A DP 0510A 5 HR 21 MI LATE
P		XIC		1240A	(UPRR/UPRR)	AR 0559A DP 0559A 5 HR 19 MI LATE
P		XTH		0124A	(UPRR/UPRR)	AR 0655A DP 0655A 5 HR 31 MI LATE
P	151	PSN		0202A	(NTMS/NTMS)	AR 0723A DP 0725A 5 HR 23 MI LATE
P		XBZ		0227A	*DEPARTED*	
P	62	ONA		0354A	(NTMS/NTMS)	AR 0852A DP 0853A 4 HR 59 MI LATE
P	8	POS		0404A	(NTMS/NTMS)	AR 0900A DP 0903A 4 HR 59 MI LATE
P		XEL		0505A	(UPRR/UPRR)	AR 0939A DP 0939A 4 HR 34 MI LATE
P	30	LAX	0535A		(4355/)	AR 1001A 4 HR 26 MI LATE
			RMK:...	(4355 05SEP22) TRK 9		

NOL-BMT Conductor=landje

iacobaj	0 SED	NOL-XSU	DSR	001	CC	Per bulletin Other, MP 908.73, 10, 1, Other, ., 10, 1, Other, ., ., .
landje	1 SED	XSU-XEB	DCS	005	UP	Restrictive signal(s) from unknown cause Stop, Control Point, E Bridge Jct
landje	2 SED	XSU-XEB	FTI	012	CC	Cross Traffic unkwn frt, Control Point, E Bridge Jct
landje	3 SED	XSU-XEB	DSR	003	CC	Per bulletin Milepost, 908.73, 908.5, 10, 1, Milepost, 908.5, 906.4, 25, 1
landje	4 SED	XWB-XLL	DCS	002	UP	Restrictive signal(s) from unknown cause NAR, Stop, Control Point, XLL
landje	5 SED	XWB-XLL	FTI	016	BN	Meet Freight train on BN main; our route 2-C; 105 track, BN 8278 E, Other, BN Avondale yd
landje	6 SED	XLL-SCH	DSR	005	BN	Per bulletin Milepost, 16.9, 17.0, 25, 1, Milepost, 21.1, 21.3, 25, 1, Milepost, 38.5, 39.5, 55, 1

landje	7 SED	XLL-SCH	DSR	002 BN	Per dispatcher (radio/phone) Milepost, 34.5, 35.1, 45, 1
landje	8 SED	SCH-NIB	SYS	004 BN	Delay in Block
landje	9 SED	SCH-NIB	DSR	002 BN	Per bulletin Milepost, 81.5, 81.8, 30, 1, Milepost, 114.0, 114.4, 25, 1
landje	10 SED	SCH-NIB	RTE	007 BN	Line manual or spring switch Siding, ess Baldwin
landje	11 SED	SCH-NIB	DSR	001 BN	Per dispatcher (radio/phone) Milepost, 119.3, 119.6, 30, 1
landje	12 SED	NIB-LFT	SYS	002 BN	Delay in Block
landje	13 SED	LFT-XIJ	WTR	000 BN	Flash flood warning Milepost, 157, 178
landje	14 SED	LCH-LCH	ADA	001 UP	Mobility Impaired
landje	15 SED	LCH-BMT	DCS	000 UP	Issue with automatic road crossing protection Procedure XI, Milepost, 257.28, 257.54
BMT-SAS Conductor=00019458					
00019458	16 SWD	BMT-HOS	DCS	083 UP	CTC system failure Authorized by signal displaying stop indication mt to mt west authority #6079. Authority #6095 to pass lf306. Lf308 clear, Control Point, lf295, Control Point, lf306, Control Point, lf308
00019458	17 SWD	HOS-XWJ	DBS	030 UP	Debris blocking track (no debris strike) Debris across crossing. Held short while debris cleared. Xh in that location, Milepost, 363.81, 363.81
millsd	18 SWD	HOS-XWJ	WTR	030 UP	Power switch failure Authorized by signal displaying stop indication connecting track to mt1. Instructed by dispatcher to put all switches in hand and line for our route, Control Point, lf368, Control Point, lf368
00019458	19 SWD	HOS-XWJ	DCS	002 UP	CTC system failure Authorized by signal displaying stop indication mt2 to connecting track west authority #6143, Control Point, lf963
00019458	20 SWD	XWJ-XRB	DCS	000 UP	Issue with automatic road crossing protection Xh, Milepost, 20.13, 20.13, Milepost, 20.48, 20.48
00019458	21 SWD	XWJ-XRB	TRS	029 UP	Vehicle on track ahead Vehicle on tracks ahead, Milepost, 29.57, 29.57
00019458	22 SWD	XWJ-XRB	DCS	000 UP	Issue with automatic road crossing protection Xg. Crossings both protected by maintainer, Milepost, 19.56, 19.56, Milepost, 19.58, 19.58
00019458	23 SWD	XRB-XEA	DSR	008 UP	Per bulletin Milepost, 39.4, 39.5, 30, main, Milepost, 40.45, 40.55, 60, main, Milepost, 47.0, 47.1, 30, main, Milepost, 51.95, 52.1, 40, main, Milepost, 52.0, 52.1, 30, main, Milepost, 53.05, 53.15, 40, main, Milepost, 67.6, 68.0, 30, main
00019458	24 SWD	XEA-XFA	TRS	028 UP	Animal strike Hot cows. Knocked hoses apart between 3 cars. Class 2 air test performed, Milepost, 70.4, 70.4
00019458	25 SWD	XEA-XFA	FTI	060 UP	Follow up7383, Milepost w/Letters, 73.5, sa087
00019458	26 SWD	XKY-XKY	SVS	004 UP	Fuel Other, kirby yard
00080866	27 SWD	SAS-XHT	FTI	014 UP	Cross over or go around Adv app to app enterprise, CLE at Medina, frt unk, Milepost, 241, 258
00080866	28 SWD	SAS-XHT	DSR	004 UP	Per bulletin Milepost, 212.63, 212.68, 30, m1, Milepost, 214.7, 214.75, 50, m1, Milepost, 232.55, 232.65, 60, m, Milepost, 235.10, 235.25, 55, m, Milepost, 258.0, 258.10, 70, m
00080866	29 SWD	XHT-XPF	DSR	005 UP	Per bulletin Milepost, 274.75, 276.75, 30, ? m, Milepost, 276.75, 279.50, 45, m, Milepost, 321.75, 322.15, 45, m, Milepost, 322.90, 323.10, 45, m
00080866	30 SWD	XHT-XPF	FTI	005 UP	Meet Milepost, 276, 280, UP 6299
00080866	31 SWD	XHT-XPF	DCS	039 UP	Power switch failure Into hand line for movement, Control Point, WE Seco
00080866	32 SWD	XPF-DRT	DSR	006 UP	Per bulletin Milepost, 352.40, 352.50, 70, m, Milepost, 360.45, 360.65, 40, m, Milepost, 366.15, 366.50, 40, m, Milepost, 368.10, 368.20, 60, m, Milepost, 369.00, 369.10, 70, m, Milepost, 371.9, 372.00, 60, m
00080866	33 SWD	DRT-XLY	FTI	109 UP	Follow No fitter, UP 6681, Milepost, 390, 443
00080866	34 SWD	XLY-SND	FTI	059 UP	Follow Milepost, 441, 482, UP 6681
00035722	35 SWD	SND-ALP	FTI	042 UP	Pick up / drop off freight crew patch, Control Point, MARATHON
00035722	36 SWD	ALP-ALP	HLD	008 UP	Passenger and/or baggage
00035722	37 SWD	XVL-XTS	DSR	006 UP	Per bulletin Milepost, 740.10, 740.20, 25, mt
00035722	38 SWD	XTS-ELP	FTI	004 UP	Follow up6213w, Control Point, BELEN, Control Point, campbell
ELP-MRC Conductor=00812091					
00812091	39 SWD	ELP-DEM	RTE	018 UP	Run via siding or slower track due to N.A.R. Milepost, 1295, 1273
00812091	40 SWD	ELP-DEM	DSR	008 UP	Per dispatcher (radio/phone) DNE Restricted Speed at MP 1210.58 MT2 No Flags, Milepost, 1210.58, 1208, 5, MT2
00812091	41 SWD	DEM-LDB	DCS	002 UP	Diverging Clear County Line MT 1 to MT 2 Control Point, County Line

00812091	42	SWD	BEN-TUS	FTI	010	UP	Follow UP West, Milepost, 988, 985
00812091	43	SWD	TUS-MRC	FTI	006	UP	Follow UP West, Milepost, 938, 927
MRC-LAX Conductor=00086817							
00086817	44	SWD	MRC-MRC	SYS	020	UP	LA crew setback a little too much, time needed to print warrants, brief, then do turnover briefing with inbound ELP crew Other, MRC Station
00086817	45	SWD	MRC-XZS	SYS	004	UP	PTC-caused slow-down or penalty stop Restricted speed to first signal, Milepost, 897.8, 896.9
00086817	46	SWD	MRC-XZS	FTI	017	UP	Follow UP8813 w, Milepost, 887.2, 857.4
00086817	48	SWD	XZS-YUM	PTI	002	UP	Meet AMTK 2, Control Point, SP785 Colfred
00086817	47	SWD	YUM-YUM	HLD	002	UP	Passenger and/or baggage
00086817	49	SWD	XIC-XTH	FTI	009	UP	Meet Control Point, SP637 Salton, UP8483 e
00086817	50	SWD	XIC-XTH	FTI	003	UP	Cross over or go around UP7084 w, Control Point, SP767 Iris
00086817	51	SWD	PSN-ONA	FTI	002	UP	Cross over or go around UP7724 e, Control Point, SP568 Banning
00086817	52	SWD	POS-XEL	FTI	017	UP	Meet UP7495 e, Control Point, AL497 W Bassett
00086817	53	SWD	XEL-LAX	OTH	003	SC	Insufficient run time