

1 20SEP22

_UNIT 155 EDI at AMTRAK STN ELP X 148MI W DEMING NM

2022/09/22 15:43:00

E		ORL	1050A	*SUSPENDED*	DP *SUSPENDED*
E	6	WPK	1108A	*SUSPENDED*	
E		XSF	1133A	*SUSPENDED*	
E	77	DLD	1156A	*SUSPENDED*	
E	68	PAK	1242P	*SUSPENDED*	
E		XPX	1251P	*SUSPENDED*	
E	114	JAX	0220P 0235P	*SUSPENDED*	
E	1	JAX	0220P 0235P	*SUSPENDED*	
E		XB1	0256P	*SUSPENDED*	
E	66	LEC	0338P	*SUSPENDED*	
E	51	MDO	0428P	*SUSPENDED*	
E		XDF	0500P	*SUSPENDED*	
E	54	TLH	0552P	*SUSPENDED*	
C	87	CIP	0658P	*SUSPENDED*	
C	66	CSV	0825P	*SUSPENDED*	
C	63	PNS	0942P 0957P	*SUSPENDED*	
C		XFM	1057P	*SUSPENDED*	
C	59	ATR	1127P	*SUSPENDED*	
C		XTC	1213A	*SUSPENDED*	
C	44	MOE	1234A	*SUSPENDED*	
C	40	PAG	0116A	*SUSPENDED*	
C		X1G	0126A	*SUSPENDED*	
C	21	BIX	0141A	*SUSPENDED*	
C	12	GUF	0200A	*SUSPENDED*	
C	15	BAS	0223A	*SUSPENDED*	
C		XL4	0248A	*SUSPENDED*	
C		XNO	0551A	*SUSPENDED*	
C		XEJ	0600A	*SUSPENDED*	
C	76	NOL	0900A	(NTMS/NTMS)	AR 1114A DP 1114A 2 HR 14 MI LATE
		RMK:...	(7490 21SEP22) LATE TURN OF EQUIP		
C		XN7	0906A	*DEPARTED*	
C		XSU	0915A	(NTMS/NTMS)	AR 1132A DP 1132A 2 HR 17 MI LATE
C		XEB	0920A	(eDr (landje)/eDr (landje))	AR 1150A DP 1150A 2 HR 30 MI LATE
C		XWB	0940A	(eDr (landje)/eDr (landje))	AR 1209P DP 1209P 2 HR 29 MI LATE
C		XLL	0954A	(eDr (landje)/eDr (landje))	AR 1228P DP 1228P 2 HR 34 MI LATE
C	56	SCH	1030A	(NTMS/NTMS)	AR 0121P DP 0122P 2 HR 52 MI LATE
C	72	NIB	1156A	(NTMS/NTMS)	AR 0240P DP 0240P 2 HR 44 MI LATE
C	18	LFT	1224P	(NTMS/NTMS)	AR 0303P DP 0306P 2 HR 42 MI LATE
C		XIJ	0143P	(BNSF/BNSF)	AR 0443P DP 0443P 3 HR LATE
C	74	LCH	0155P	(NTMS/NTMS)	AR 0507P DP 0509P 3 HR 14 MI LATE
C		XFC	0245P	*DEPARTED*	
C	60	BMT	0334P 0348P	(NTMS/NTMS)	AR 0705P DP 0718P 3 HR 30 MI LATE
		RMK:...	(3360 21SEP22) MEET UP-1961 AT CONNELL (E/BMT)		
C		XCB	0448P	*DEPARTED*	
C	82	HOS	0618P 0655P	(NTMS/NTMS)	AR 0918P DP 0938P 2 HR 43 MI LATE
C		XWJ	0720P	(UPRR/UPRR)	AR 1002P DP 1002P 2 HR 42 MI LATE
C		XRb	0746P	(UPRR/UPRR)	AR 1030P DP 1030P 2 HR 44 MI LATE
C		XEA	0816P	(UPRR/UPRR)	AR 1105P DP 1105P 2 HR 49 MI LATE

C		XFA		0906P	(UPRR/UPRR)	AR 1158P DP 1158P 2 HR 52 MI LATE
C		XKG		0951P	(UPRR/UPRR)	AR 1252A DP 1252A 3 HR 1 MI LATE
C		XKY	1115P	1123P	(eDr (00019458)/eDr (00019458))	AR 0146A DP 0157A 2 HR 34 MI LATE
C	215	SAS	1205A	0245A	(eDr (00019458)/NTMS)	AR 0317A DP 0500A 2 HR 15 MI LATE
C		XHT		0354A	(UPRR/UPRR)	AR 0606A DP 0606A 2 HR 12 MI LATE
C		XPF		0508A	(UPRR/UPRR)	AR 0741A DP 0741A 2 HR 33 MI LATE
C	169	DRT		0549A	(NTMS/NTMS)	AR 0820A DP 0826A 2 HR 37 MI LATE
C		XLY		0659A	(UPRR/eDr (00080866))	AR 0942A DP 0937A 2 HR 38 MI LATE
C		XAW		0740A	*DEPARTED*	
C	124	SND		0824A	(NTMS/NTMS)	AR 1101A DP 1102A 2 HR 38 MI LATE
C		XMZ		0926A	*DEPARTED*	
C	95	ALP	1028A	1038A	(NTMS/NTMS)	AR 1249P DP 0106P 2 HR 28 MI LATE
C		XVL		1138A	(UPRR/UPRR)	AR 0206P DP 0206P 2 HR 28 MI LATE
C		XTS		1233P	(UPRR/UPRR)	AR 0300P DP 0300P 2 HR 27 MI LATE
C		XMQ		1258P	*DEPARTED*	
C		XTT		0118P	*DEPARTED*	
M	219	ELP	0122P	0147P	(eDr (00802096)/NTMS)	AR 0527P DP 0543P 3 HR 56 MI LATE
			RMK:...	(3360 22SEP22) DISABLED FREIGHT ELP		
M		XLN		0222P	*DEPARTED*	
M	86	DEM		0318P	(NTMS/NTMS)	AR 0730P DP 0731P 4 HR 13 MI LATE
			RMK:...	(7783 22SEP22) ELPMRC CND ATKINS 267-667-1162 A/C SMITH TUS 2 ITEMS		
M	60	LDB		0413P	(NTMS/NTMS)	AR 0845P DP 0846P 4 HR 33 MI LATE
M		XLZ		0416P	*DEPARTED*	
M	117	BEN		0518P	(NTMS/NTMS)	AR 1012P DP 1013P 4 HR 55 MI LATE
M	47	TUS	0645P	0735P	(NTMS/NTMS)	AR 1132P DP 1210A 4 HR 35 MI LATE
M		XRE		0758P	*DEPARTED*	
M		XCG		0831P	*DEPARTED*	
M	85	MRC	0852P	0902P	(eDr (00807650)/NTMS)	AR 0126A DP 0143A 4 HR 41 MI LATE
M		XZS		0955P	(eDr (00812287)/eDr (00812287))	AR 0242A DP 0242A 4 HR 47 MI LATE
M		XWZ		1048P	*DEPARTED*	
M	165	YUM		1149P	(NTMS/NTMS)	AR 0427A DP 0433A 4 HR 44 MI LATE
P		XIC		1240A	(UPRR/UPRR)	AR 0655A DP 0655A 6 HR 15 MI LATE
P		XTH		0124A	(UPRR/UPRR)	AR 0742A DP 0742A 6 HR 18 MI LATE
P	151	PSN		0202A	(NTMS/NTMS)	AR 0810A DP 0812A 6 HR 10 MI LATE
			RMK:...	(7658 23SEP22) FREIGHT INTERFERENCE W/YUM		
P		XBZ		0227A	*DEPARTED*	
P	62	ONA		0354A	(NTMS/NTMS)	AR 0953A DP 0957A 6 HR 3 MI LATE
P	8	POS		0404A	(eDr (00812287)/eDr (00812287))	AR 1002A DP 1002A 5 HR 58 MI LATE
P		XEL		0505A	(eDr (00812287)/eDr (00812287))	AR 1025A DP 1025A 5 HR 20 MI LATE
P	30	LAX	0535A		(4493/)	AR 1052A 5 HR 17 MI LATE
			RMK:...	(4493 23SEP22) TRACK 13		

NOL-BMT Conductor=landje

landje	0 SED	NOL-NOL	ITI	134 AM	Service, turn, or wye train 02
landje	1 SED	NOL-XSU	DCS	008 CC	Restrictive signal(s) from known wayside signal failure Wait for signal to timeout, Stop, Control Point, XSU
landje	9 SED	XSU-XEB	DCS	010 UP	Restrictive signal(s) from unknown cause Stop, Control Point, E Bridge Jct
landje	10 SED	XSU-XEB	DSR	003 CC	Per bulletin Milepost, 908.73, 908.5, 10, 1, Milepost, 908.5, 906.4, 25, 1
landje	4 SED	XWB-XLL	FTI	004 BN	Meet Freight train clearing in BN Avondale yd, BN 4341 E, Control Point, RCPS 124
landje	5 SED	XWB-XLL	DCS	008 BN	Restrictive signal(s) from known wayside signal failure Restricted speed on BN main, Restricting, Milepost w/Letters, XWB, XLL
landje	6 SED	XLL-SCH	SYS	004 BN	Delay in Block

landje	7 SED	XLL-SCH	DSR	003	BN	Per bulletin Milepost, 16.9, 17.0, 25, 1, Milepost, 21.1, 21.3, 25, 1, Milepost, 37.6, 37.8, 40, 1, Milepost, 38.5, 39.5, 55, 1
landje	8 SED	XLL-SCH	FTI	009	BN	Lined switch behind freight train BN 6403 W, Siding, ess Raceland
landje	11 SED	SCH-NIB	DSR	000	BN	Per bulletin Milepost, 81.5, 81.8, 30, 1
landje	12 SED	NIB-LFT	SYS	001	BN	Delay in Block
landje	13 SED	LFT-XIJ	DSR	002	BN	Per dispatcher (radio/phone) Milepost, 167.5, 168.0, 15, 1
landje	14 SED	LFT-XIJ	DCS	021	BN	Restrictive signal(s) from unknown cause Delay: 1549-1619, Approach medium, Approach, Stop 2x, Restricting, Clear, Milepost, 170.3, 182.5
landje	15 SED	LFT-XIJ	DSR	003	BN	Per bulletin Milepost, 147.9, 148.4, 30, 1, Milepost, 183.0, 183.9, 30, 1
landje	16 SED	XIJ-LCH	FTI	007	UP	Cross Traffic Unknown freight clearing at scale track, unkwn frt, Control Point, 218
landje	17 SED	LCH-BMT	DSR	001	UP	Per dispatcher (radio/phone) Milepost, 252.25, 252.75, 30, 1
landje	18 SED	LCH-BMT	FTI	035	UP	Meet Crew running short on time, Siding, Connell, UP 1961 E, local
landje	19 SED	LCH-BMT	DCS	001	UP	Issue with automatic road crossing protection Other, MP 220.8
BMT-SAS Conductor=00019458						
00019458	20 SWD	BMT-HOS	FTI	016	UP	Blocked from station track Sent on mt1 around Houston and backed into Houston depot due to freight train being parked on east end of depot track, up, Control Point, If 368
00019458	21 SWD	XWJ-XRB	DSR	002	UP	Per bulletin Milepost, 15.0, 15.35, 15, 1, Milepost, 23.0, 23.1, 30, 2
00019458	22 SWD	XR-B-XEA	DSR	005	UP	Per bulletin Milepost, 51.95, 52.1, 40, main, Milepost, 52.0, 52.1, 30, main, Milepost, 68.55, 68.65, 25, main
00019458	23 SWD	XEA-XFA	DSR	003	UP	Per bulletin Milepost, 102.45, 102.65, 60, main, Milepost, 103.8, 103.9, 60, main, Milepost, 109.75, 110.0, 60, main, Milepost, 111.1, 111.2, 60, main, Milepost, 112.9, 113.0, 60, main, Milepost, 116.65, 116.8, 60, main, Milepost, 118.0, 118.1, 30, main
00019458	24 SWD	XFA-XKG	FTI	004	UP	Cross over or go around up8734, Control Point, sa120, Control Point, sa123
00019458	25 SWD	XFA-XKG	FTI	005	UP	Cross over or go around up7652, Control Point, sa161, Control Point, sa165
00019458	26 SWD	XKG-XKY	DCS	013	UP	Restrictive signal(s) from unknown cause Running on clears. Signal at sa176 dropped red. Stopped short of signal. Authorized to pass signal displaying stop indication authority #4134 mt - mt west 0107 rab, Stop, Control Point, sa176
00019458	27 SWD	XKY-XKY	SVS	003	UP	Fuel Other, kirby yard
00019458	28 SWD	XKY-SAS	FTI	063	UP	Cross Traffic Train ahead waiting for eot and recrew, kcs4842, Control Point, sa208
SAS-ALP Conductor=00080866						
00080866	29 SWD	SAS-XHT	DSR	006	UP	Per bulletin Milepost, 212.63, 212.68, 30, m1, Milepost, 212.95, 213.00, 30, m1, Milepost, 213.82, 213.87, 30, m1, Milepost, 214.7, 214.75, 30, m1, Milepost, 216.7, 216.75, 30, m1, Milepost, 232.55, 232.65, 60, m, Milepost, 233.55, 233.65, 55, m, Milepost, 235.10, 235.35, 25, m, Milepost, 240.35, 24
00080866	30 SWD	XHT-XPF	FTI	019	UP	Follow Follow 301 303 around 305 308, Unk, Milepost, 301, 308
00080866	31 SWD	XHT-XPF	DSR	002	UP	Per bulletin Milepost, 277.65, 277.75, 60, m, Milepost, 366.15, 366.50, 40, m
00080866	32 SWD	XPF-DRT	DMW	002	UP	Waiting for MW clearance Milepost, 378.25, 379.0
00080866	33 SWD	XPF-DRT	DSR	002	UP	Per bulletin Milepost, 366.15, 366.50, 40, m
00080866	34 SWD	DRT-DRT	ADA	004	UP	Service animals SVC Dog potty break
00080866	35 SWD	XLY-SND	FTI	002	UP	Cross over or go around Siding, langtry, UP 7806
00080866	36 SWD	XLY-SND	DSR	004	UP	Per bulletin Milepost, 464.25, 464.35, 30, ?m, Milepost, 466.35, 466.45, 40, m, Milepost, 484.97, 485.03, 70, m, Milepost, 485.60, 485.70, 25, m
00080866	38 SWD	SND-ALP	OTH	007	UP	Lost time - N.A.R. There is no reason that we lost this much time.
00080866	39 SWD	SND-ALP	DSR	002	UP	Per bulletin Milepost, 563.80, 563.90, 60, m, Milepost, 589.53, 589.63, 30, m
ALP-ELP Conductor=00802096						
00802096	37 SWD	ALP-ALP	HLD	007	UP	Multiple spots
00802096	40 SWD	XTS-ELP	DSR	004	UP	Per bulletin NFD, Milepost, 760, 760.9, 25, main
00802096	41 SWD	XTS-ELP	FTI	099	UP	Blocked from station track UP 6280, Control Point, Civic Center
00802096	42 SWD	XTS-ELP	PTI	013	UP	Meet UP 6452, Siding, Lasca

ELP-MRC Conductor=00807650

00807650	43	SWD	ELP-DEM	DCS	014	UP	Restrictive signal(s) from unknown cause Restricted Proceed, Milepost, 1256, 1251
00807650	44	SWD	ELP-DEM	FTI	011	UP	Cross over or go around UP 7455, Milepost, 1276, 1268
00807650	45	SWD	DEM-LDB	FTI	026	UP	Follow UP 7602, Milepost, 1191, 1170
00807650	46	SWD	LDB-BEN	FTI	031	UP	Follow UP 8930, Milepost, 1101, 1089
00807650	47	SWD	BEN-TUS	RTE	026	UP	Run via siding or slower track due to N.A.R. Milepost, 1032, 1000
00807650	48	SWD	TUS-MRC	SYS	004	UP	Re-crew / job briefing

MRC-LAX Conductor=00812287

00812287	49	SWD	MRC-MRC	ADA	003	UP	Vision / hearing-impaired Changing cars due to out of service bathrooms
00812287	50	SWD	MRC-MRC	SYS	004	UP	Re-crew / job briefing Control Point, MRC
00812287	51	SWD	MRC-XZS	FTI	006	UP	Meet UP 9016, Control Point, W. Gila Bend
00812287	52	SWD	XZS-YUM	FTI	008	UP	Meet UP, Control Point, 772
00812287	53	SWD	XZS-YUM	DSR	003	UP	Per bulletin Milepost, 250, 249, 30, 1
00812287	54	SWD	YUM-YUM	ADA	002	UP	Mobility Impaired
00812287	55	SWD	YUM-XIC	DSR	031	UP	Per dispatcher (radio/phone) Red @ Glamis. Broken rail at mesquite, Milepost, 699, 694, 20, 1
00812287	56	SWD	YUM-XIC	FTI	063	UP	Meet UP 7859, Control Point, cactus
00812287	57	SWD	XIC-XTH	DSR	003	UP	Sinkhole Milepost, 663, 661, 30, 1
00812287	58	SWD	PSN-ONA	DCS	008	UP	Restrictive signal(s) from unknown cause Restricted proceed, Milepost, 563, 561
00812287	59	SWD	PSN-ONA	FTI	008	UP	Cross over or go around UP 2576, Milepost, 562, 558
00812287	60	SWD	POS-XEL	DSR	004	UP	Per bulletin Control Point, bassett, 15, 1
00812287	61	SWD	XEL-LAX	DMW	008	SC	Waiting for MW clearance Longmore and McIntyre, Milepost, 494, 484