

2 06MAY22

_UNIT 142 EDI at AMTRAK STN LFT X 89MI E NEW IBERIA LA

2022/05/08 21:21:00

P		LAX		1000P	(/NTMS)	DP 1001P 1 MI LATE
			RMK:..	(1388 06MAY22) TRACK# 12		
P		XEL		1018P	(UPRR/UPRR)	AR 1025P DP 1025P 7 MI LATE
P	30	POS		1041P	(NTMS/NTMS)	AR 1141P DP 1230A 1 HR 49 MI LATE
			RMK:..	(7658 06MAY22) DLY'D FRT INTERFERENCE; UP2586 EXP CREW		
P	8	ONA		1054P	(NTMS/NTMS)	AR 0101A DP 0108A 2 HR 14 MI LATE
P		XBZ		1150P	*DEPARTED*	
P	62	PSN		1236A	(NTMS/NTMS)	AR 0511A DP 0513A 4 HR 37 MI LATE
			RMK:..	(3360 07MAY22) FREIGHT INTERFERENCE YUMA SUB		
P		XTH		0104A	(UPRR/UPRR)	AR 0542A DP 0542A 4 HR 38 MI LATE
P		XIC		0145A	(UPRR/UPRR)	AR 0634A DP 0634A 4 HR 49 MI LATE
M	151	YUM		0247A	(NTMS/NTMS)	AR 0725A DP 0738A 4 HR 51 MI LATE
M		XWZ		0336A	*DEPARTED*	
M		XZS		0428A	(eDr (00753633)/eDr (00753633))	AR 1020A DP 1020A 5 HR 52 MI LATE
M	165	MRC	0530A	0540A	(NTMS/NTMS)	AR 1217P DP 1247P 7 HR 7 MI LATE
			RMK:..	(3360 07MAY22) MEDICAL EMERGENCY/POLICE ACTIVITY		
M		XCG		0557A	*DEPARTED*	
M		XRE		0627A	*DEPARTED*	
M	85	TUS	0728A	0815A	(NTMS/NTMS)	AR 0201P DP 0241P 6 HR 26 MI LATE
M	47	BEN		0915A	(NTMS/NTMS)	AR 0335P DP 0338P 6 HR 23 MI LATE
M		XLZ		1015A	*DEPARTED*	
M	117	LDB		1215P	(NTMS/NTMS)	AR 0633P DP 0636P 6 HR 21 MI LATE
M	60	DEM		0110P	(NTMS/NTMS)	AR 0724P DP 0729P 6 HR 19 MI LATE
M		XLN		0207P	*DEPARTED*	
M	86	ELP	0310P	0335P	(NTMS/NTMS)	AR 0858P DP 0917P 5 HR 42 MI LATE
			RMK:..	(6938 07MAY22) 6 BAGS		
C		XTT		0525P	*DEPARTED*	
C		XMQ		0546P	*DEPARTED*	
C		XTS		0611P	(UPRR/UPRR)	AR 1152P DP 1152P 5 HR 41 MI LATE
C		XVL		0710P	(UPRR/UPRR)	AR 1251A DP 1251A 5 HR 41 MI LATE
C	219	ALP	0835P	0845P	(NTMS/NTMS)	AR 0159A DP 0312A 6 HR 27 MI LATE
			RMK:..	(1759 08MAY22) ALP, CREW SIGN UP AT 2:25A-CT		
C		XMZ		0933P	*DEPARTED*	
C	95	SND		1036P	(NTMS/NTMS)	AR 0455A DP 0455A 6 HR 19 MI LATE
C		XAW		1113P	*DEPARTED*	
C		XLY		1154P	(UPRR/UPRR)	AR 0612A DP 0612A 6 HR 18 MI LATE
C	124	DRT		0102A	(NTMS/NTMS)	AR 0734A DP 0741A 6 HR 39 MI LATE
C		XPF		0142A	(UPRR/UPRR)	AR 0818A DP 0818A 6 HR 36 MI LATE
C		XHT		0257A	(UPRR/UPRR)	AR 0936A DP 0936A 6 HR 39 MI LATE
C	169	SAS	0450A	0625A	(NTMS/eDr (00019458))	AR 1035A DP 1214P 5 HR 49 MI LATE
C		XKY	0647A	0655A	(eDr (00019458)/eDr (00019458))	AR 1238P DP 1249P 5 HR 54 MI LATE
C		XKG		0749A	(UPRR/UPRR)	AR 0136P DP 0136P 5 HR 47 MI LATE
C		XFA		0829A	(UPRR/UPRR)	AR 0218P DP 0218P 5 HR 49 MI LATE
C		XEA		0920A	(UPRR/UPRR)	AR 0315P DP 0315P 5 HR 55 MI LATE
C		XRB		0950A	(UPRR/UPRR)	AR 0343P DP 0343P 5 HR 53 MI LATE
C		XWJ		1025A	(UPRR/UPRR)	AR 0410P DP 0410P 5 HR 45 MI LATE

C	215	HOS	1110A	1210P	(NTMS/NTMS)	AR 0436P DP 0458P 4 HR 48 MI LATE
			RMK:...	(6938 07MAY22)	STEP BOX PROTO TYPE HEADING YOUR WAY	
C		XCB		1251P	*DEPARTED*	
C	82	BMT	0153P	0205P	(eDr (00019458)/NTMS)	AR 0730P DP 0743P 5 HR 38 MI LATE
			RMK:...	(1759 08MAY22)	HOS-BMT, OPR BMT SUB (+29"), SPEED RESTR & CROSSING PROTECT (+30").	
C		XFC		0230P	*DEPARTED*	
C	60	LCH		0329P	(NTMS/NTMS)	AR 0856P DP 0900P 5 HR 31 MI LATE
C		XIJ		0400P	(BNSF/BNSF)	AR 0912P DP 0912P 5 HR 12 MI LATE
C	74	LFT	0512P	0515P	(NTMS/NTMS)	AR 1015P DP 1018P 5 HR 3 MI LATE
C	18	NIB		0541P	(NTMS/NTMS)	AR 1040P DP 1040P 4 HR 59 MI LATE
C	72	SCH		0703P	(NTMS/NTMS)	AR 1203A DP 1203A 5 HR LATE
C		XLL		0822P	(eDr (landje)/eDr (landje))	AR 1248A DP 1255A 4 HR 33 MI LATE
C		XWB		0828P	(eDr (landje)/eDr (landje))	AR 0130A DP 0130A 5 HR 2 MI LATE
C		XEB		0847P	(eDr (landje)/eDr (landje))	AR 0210A DP 0210A 5 HR 23 MI LATE
C		XSU		0852P	(NTMS/NTMS)	AR 0229A DP 0229A 5 HR 37 MI LATE
C		XN7		0912P	*DEPARTED*	
C	56	NOL	0940P		(1759/)	AR 0250A 5 HR 10 MI LATE
			RMK:...	(1759 08MAY22)	EAST BRIDGE, CROSS TRAFFIC	

LAX-MRC Conductor=00809890

00809890	1	SWD	LAX-XEL	FTI	006	UP	Follow eb up, Control Point, valley blvd
00809890	0	SWD	XEL-POS	FTI	056	UP	Blocked from station track 2586, Control Point, marne
00809890	2	SWD	POS-POS	FTI	046	UP	Meet 7844, Control Point, hamilton
00809890	3	SWD	POS-ONA	FTI	023	UP	Shoved out of POS station due to dead train ahead. Met another train and Waited for it to clear before getting access to station track. Control Point, n ontario, dead 2586 then wb up
00809890	4	SWD	ONA-ONA	ADA	004	UP	Mobility Impaired
00809890	5	SWD	ONA-PSN	FTI	161	UP	Follow Follow to PSN, eb up, Control Point, loma linda
00809890	6	SWD	XTH-XIC	FTI	011	UP	Meet Control Point, mortmar, 8476
00809890	7	SWD	XIC-YUM	FTI	004	UP	Meet Control Point, clyde, wb up
WooldrS	8	SWD	YUM-YUM	TRS	008	UP	Last chance for fare evader - he failed, Other, .

XZS-DEM Conductor=00753633

00753633	9	SWD	XZS-MRC	FTI	034	UP	Meet up3076w, Control Point, mobile
00753633	10	SWD	XZS-MRC	FTI	030	UP	Meet up5405w, Control Point, sentinel

MRC-ELP Conductor=00810389

MRC-ELP Conductor=00810389

00753633	11	SWD	MRC-MRC	HLD	007	UP	Multiple spots
00753633	12	SWD	MRC-MRC	ADA	005	UP	Service animals
00753633	13	SWD	MRC-MRC	POL	008	UP	Removal of passenger by police
00753633	14	SWD	BEN-BEN	HLD	001	UP	Multiple spots
00753633	15	SWD	LDB-LDB	HLD	002	UP	Multiple spots
00810389	16	SWD	DEM-DEM	HLD	004	UP	Multiple spots
00035722	17	SWD	XTS-XVL	FTI	004	UP	Cross over or go around UP8705, Control Point, MALLIE
00035722	18	SWD	XVL-ALP	FTI	009	UP	Meet UP2571, Control Point, Ryan

ALP-SAS Conductor=00080866

00080866	19	SWD	ALP-ALP	SYS	063	UP	Set back for outbound crew on duty 225am. Procure TCS and Hold proper job briefing. Perform class 2 and initialize PTC, Other, Alpine
00080866	20	SWD	ALP-SND	SYS	005	UP	Delay in Block Milepost, 606.2, 603.9
00080866	25	SWD	XLY-DRT	OTH	006	UP	Lost time - N.A.R. Insufficient run time
00080866	26	SWD	XLY-DRT	PTI	010	UP	Meet amtk 1, Control Point, EE Feely
00080866	27	SWD	DRT-DRT	ADA	002	UP	Mobility Impaired
00080866	28	SWD	DRT-DRT	HLD	003	UP	High passenger count

00080866	29	SWD	XPF-XHT	DSR	003	UP	Per bulletin Milepost, 328, 327.95, 25, m, Milepost, 320.35, 320.25, 25, m, Milepost, 319.95, 319.15, 40, m, Milepost, 295.15, 295.05, 60, m, Milepost, 277.25, 277, 70, m, Milepost, 263.75, 263.50, 70, m
SAS-BMT Conductor=00019458							
00019458	30	SWD	SAS-SAS	SVS	004	UP	Normal switch / set out / pick up of locomotives, cars or section of train Set over 422 transfer cars to ground power on depot 3, Other, sas depot
00019458	31	SWD	SAS-SAS	RTE	000	UP	Waiting for authority onto mt1 authority #3554 1215 rll Other, sas depot
00019458	32	SWD	SAS-XKY	RTE	004	UP	Line manual or spring switch Line ourselves out onto mt1 and line behind. No yard job, Milepost, 209.13, 209.13
00019458	33	SWD	XKY-XKY	SVS	003	UP	Fuel Other, kirby yard
00019458	34	SWD	XKY-XKG	FTI	008	UP	Meet up7708, Control Point, sa189
00019458	35	SWD	XKG-XFA	DSR	002	UP	Per bulletin Milepost, 153.1, 153.0, 50, main, Milepost, 127, 126.8, 40, main
00019458	36	SWD	XFA-XEA	FTI	007	UP	Meet up8973, Control Point, sa113
00019458	37	SWD	XRb-XWJ	FTI	001	UP	Meet bnsf8394, Control Point, sa014
00019458	38	SWD	XWJ-HOS	FTI	002	UP	Cross over or go around up4063, Control Point, lf372, Control Point, lf369
00019458	39	SWD	HOS-BMT	RTE	029	UP	Routed BMT sub unable to make scheduled runtime Control Point, lf365
00019458	40	SWD	HOS-BMT	DSR	022	UP	Per bulletin Milepost, 394.3, 395.3, 25, main, Milepost, 399.95, 400.05, 40, main, Milepost, 409.5, 414.5, 25, main, Milepost, 415.45, 416.45, 30, main, Milepost, 417, 418.25, 30, main, Milepost, 427.25, 428, 15, main
BMT-NOL Conductor=landje							
landje	41	SED	BMT-BMT	SVS	001	UP	Initializing PTC (no failure)
landje	42	SED	BMT-LCH	FTI	000	UP	Meet Control Point, Station 14, UP 6005 W
landje	43	SED	BMT-LCH	DCS	000	UP	Issue with automatic road crossing protection Other, MP 220.8
landje	44	SED	BMT-LCH	DSR	000	UP	Per bulletin Milepost, 220.25, 220.1, 30, 1
landje	45	SED	LCH-LCH	HLD	002	UP	Passenger and/or baggage
landje	46	SED	XIJ-LFT	DSR	000	BN	Per bulletin Milepost, 181.0, 180.7, 60, 1
landje	47	SED	NIB-SCH	DSR	002	BN	Per bulletin Milepost, 124.3, 124.1, 10, 1, Milepost, 114.3, 114.1, 30, 1, Milepost, 95.8, 95.6, 60, 1, Milepost, 81.8, 81.5, 30, 1, Milepost, 73.4, 73.3, 25, 1, Milepost, 70.0, 69.9, 40, 1
landje	48	SED	SCH-XLL	DSR	003	BN	Per bulletin Milepost, 39.5, 38.5, 55, 1, Milepost, 21.3, 21.1, 40, 1, Milepost, 17.0, 16.9, 25, 1
landje	49	SED	XLL-XLL	DCS	007	UP	Restrictive signal(s) from known wayside signal failure Wait on signal to timeout, Stop, Control Point, XLL
landje	50	SED	XLL-XWB	FTI	027	UP	Cross over or go around Freight train on BN main; our route 108 track, 2-B, Other, Avondale BN yd, BN 8065 E
landje	51	SED	XWB-XEB	DCS	021	CC	Restrictive signal(s) from known wayside signal failure Wait on CC to accept UP signal request, Stop, Control Point, E Bridge Jct
landje	52	SED	XEB-XSU	DSR	005	CC	Per bulletin Milepost, 906.4, 908.5, 25, 1, Milepost, 907.8, 908.0, 5, 1, Milepost, 908.5, 908.73, 10, 1
landje	53	SED	XEB-XSU	DCS	009	CC	Restrictive signal(s) from unknown cause Stop, Clear, Milepost w/Letters, Long X-over, CTC XSU
landje	54	SED	XSU-NOL	DSR	002	AM	Per bulletin Other, MP 908.73, 10, 1