

AB-33-228X

EI-1961



Simon Monroe
 <Simon.Monroe@noaa.gov>
 03/31/2006 01:38 PM

To

cc Simon Monroe <Simon.Monroe@noaa.gov>, Marti Ikehara
 <Marti.Ikehara@noaa.gov>, Gilbert Mitchell
 <Gilbert.Mitchell@noaa.gov>, pat.canfield@acsm.net,

bcc

Subject NGS Response, STB docket AB-33 (SUB NO. 228X)

Mack Shumate (no email; sent via post.)
 Thank you for sharing your railroad abandonment environmental report for
 Holtville, Imperial County, California

Approximately 40 geodetic survey marks may be located in the area
 described. If marks will be disturbed by the abandonment, NGS requests
 90-day advance notice to attempt their formal relocation. These marks
 are described on the attached file. Additional advice is provided at
<http://geodesy.noaa.gov/marks/railroads/>

Dist	PID...	H V	Vert_Source	Approx.	Approx..	Stab	Designation
----	-----	-	-	-----	-----	----	-----
....	DB0652	.	1	29/ADJUSTED	N324836	W1152248	B... -10 Y
....	DB0641	.	1	88/ADJUSTED	N324829	W1152303	B... B 1224
....	DB1218	.	1	88/ADJUSTED	N324824	W1152354	C... CO J 4
....	DB0650		1	88/ADJUSTED	N324830	W1152255	C... HOLTVILLE
....	DB1450		3		N324831	W1152256	 HOLTVILLE MUNICIPAL TANK
....	DB1451		3		N324832	W1152255	 HOLTVILLE OLD MUNICIPAL TANK
....	DB0655	.	1	88/ADJUSTED	N324830	W1152256	D... HOLTVILLE RM 1
....	DB0651	.	m	88/READJUST	N324827	W1152255	C... HOLTVILLE RM 2
....	DB0648	.	1	29/ADJUSTED	N324825	W1152321	C... HOLTVILLE RM 3
....	DB0649		1	88/ADJUSTED	N324830	W1152256	C... HOLTVILLE RM 4
....	DB0654		1	88/ADJUSTED	N324835	W1152249	C... J 60
....	DB0570	.	1	29/ADJUSTED	N324834	W1152219	D... J 613
....	DB0569	.	1	88/ADJUSTED	N324835	W1152218	D... J 613 RESET
....	DB0568	.	3	29/RESET...	N324835	W1152217	B... J 613 RESET 1965
....	DB1166	.	1	88/ADJUSTED	N324833	W1152303	A... N 1362
....	DB0639	.	1	29/ADJUSTED	N324826	W1152323	C... N 91
....	DB0640	.	m	88/READJUST	N324827	W1152319	B... N 91 RESET
....	DB1719	.	1	88/ADJUSTED	N324827	W1152319	D... N 91 RESET

|....|DB0653|. 1|88/ADJUSTED|N324836|W1152249|C...|P 91
|....|DB0571|. 1|29/ADJUSTED|N324835|W1152216|D...|V 1223
|....|DB1851|. 3|29/RESET...|N324835|W1152216|D...|V 1223 RESET
|....|DB0638|. 1|88/ADJUSTED|N324824|W1152353|C...|X 59
|....|DB1217|. 1|88/ADJUSTED|N324823|W1152423|C...|CO J 5
|....|DB0634|. 1|88/ADJUSTED|N324819|W1152515|C...|L 91
|....|DB0619|. 1|88/ADJUSTED|N324815|W1152756|C...|K 1223
|....|DB0612|. 1|88/ADJUSTED|N324757|W1152955|D...|-47
|....|DB1516|. 3|. |.....|N324759|W1153017|....|EL CENTRO COMPRESS CO
WATER TK
|....|DB0695|. 1|88/ADJUSTED|N324759|W1153004|C...|H 1223
|....|DB0613|. 1|29/ADJUSTED|N324808|W1152904|D...|H 91
|....|DB0615|. 1|88/ADJUSTED|N324809|W1152902|C...|H 91 RESET
|....|DB0614|. 3|29/RESET...|N324808|W1152904|D...|H 91 RESET 1950
|....|DB0617|. 1|88/ADJUSTED|N324812|W1152827|C...|J 1223
|....|DB0616|. 1|29/ADJUSTED|N324813|W1152837|C...|J 91
|....|DB1167|. 1|88/ADJUSTED|N324757|W1153006|A...|M 1362
|....|DB1752|. 1|. |29/GPS OBS.|N324811|W1152903|C...|MEADOWS 2
|....|DB0618|. 1|29/ADJUSTED|N324812|W1152825|C...|MELLO RM 2
|....|DB0693|. 1|29/ADJUSTED|N324759|W1153005|C...|U 59
|....|DB0694|. ?|29/ADJUSTED|N324759|W1153005|C...|U 59 RESET 1953
|....|DB0696|. m|88/READJUST|N324759|W1153005|B...|Z 1223
|....|DB1168|. A 1|88/ADJUSTED|N324747|W1153106|C...|L 1362