



Simon Monroe
<Simon.Monroe@noaa.gov>

03/27/2007 05:56 PM

To llbellis@ggelaw.com

cc Surface Transportation Board <sea@stb.dot.gov>, National
Society of Professional Surveyors
<Dawn.James@acsm.net>, Gilbert Mitchell

bcc

Subject [NGS Response, STB docket AB-369 (SUB NO. 6X)]
-STBdocket AB-976(SUB NO. 2X -STB docket AB-1004(X)]

688 - 3X
276 - 2X
004 - 0X
EI-2982
CB

Thank you for sharing your railroad abandonment environmental report for
Clarion County, Lawton, PENNSYLVANIA.

Approximately 051 geodetic survey marks may be located in the area
described. If marks will be disturbed by the abandonment, NGS requests
90-day advance notice to attempt their formal relocation. These marks
are described on the attached file. Additional advice is provided at
<http://geodesy.noaa.gov/marks/railroads/>

|Dist|PID...|H V|Vert_Source|Approx.|Approx..|Stab|Designation

|----|-----| - -|-----|-----|-----|----|-----

|....|TE0905|. 2|88/ADJUSTED|N483750|W0984509|C...|A 408

|....|TE0943|. 2|88/ADJUSTED|N483657|W0984523|C...|F 56

|....|TE0944|. 2|88/ADJUSTED|N483744|W0984628|C...|G 56

|....|TE0941|. 2|88/ADJUSTED|N483538|W0984337|C...|E 56

|....|TE0942|. 2|88/ADJUSTED|N483606|W0984412|C...|Q 259

|....|TE0940|. 2|88/ADJUSTED|N483454|W0984235|C...|D 56

|....|TE0939|. 2|88/ADJUSTED|N483453|W0984232|C...|P 259

|....|TE0936|. 2|88/ADJUSTED|N483333|W0984040|C...|C 56

|....|TE0935|. 2|88/ADJUSTED|N483256|W0983952|C...|L 259

|....|TE0937|. 2|88/ADJUSTED|N483333|W0984040|C...|M 259

|....|TE0933|. 2|88/ADJUSTED|N483221|W0983903|C...|A 56

|....|TE0934|. 2|88/ADJUSTED|N483241|W0983928|C...|B 56

|....|TE0931|. 2|88/ADJUSTED|N483145|W0983807|C...|K 259

|....|TE1084|. 2|88/ADJUSTED|N483237|W0983840|B...|Z 414

|....|TE0932|. 2|88/ADJUSTED|N483204|W0983839|C...|Z 55

|....|TE0928|. 2|88/ADJUSTED|N483021|W0983601|C...|H 259

|....|TE0930|. 2|88/ADJUSTED|N483114|W0983722|C...|J 259

|....|TE1044|. 2|88/ADJUSTED|N483053|W0983604|C...|U 190

|....|TE0929|. 2|88/ADJUSTED|N483038|W0983631|C...|Y 55
|....|TE0730|. 2|88/ADJUSTED|N482949|W0983517|C...|G 259
|....|TE0731|. 2|88/ADJUSTED|N482908|W0983521|C...|R 260
|....|TE0732|. 2|88/ADJUSTED|N482907|W0983529|C...|S 260
|....|TE0729|. 3|29/RESET...|N482907|W0983419|C...|X 55 RESET
|....|TE0726|. 2|88/ADJUSTED|N482749|W0983212|C...|E 259
|....|TE0727|. 2|88/ADJUSTED|N482837|W0983329|C...|F 259
|....|TE0723|. 2|88/ADJUSTED|N482653|W0983050|C...|C 259
|....|TE0725|. 2|88/ADJUSTED|N482723|W0983137|C...|D 259
|....|TE0724|. 2|88/ADJUSTED|N482701|W0983102|C...|V 55
|....|TE0370|. 2|88/ADJUSTED|N482601|W0982930|C...|A 259
|....|TE0722|. 2|88/ADJUSTED|N482633|W0983020|C...|B 259
|....|TE0369|. 2|88/ADJUSTED|N482550|W0982914|C...|U 55
|....|TE0480|. 2|88/ADJUSTED|N482448|W0982656|C...|F 412
|....|TE0366|. 2|88/ADJUSTED|N482431|W0982714|C...|T 55
|....|TE0367|. 2|88/ADJUSTED|N482448|W0982742|C...|Y 258
|....|TE0478|. 2|88/ADJUSTED|N482447|W0982812|D...|Y 272
|....|TE0363|. 2|88/ADJUSTED|N482303|W0982507|C...|V 258
|....|TE0364|. 2|88/ADJUSTED|N482327|W0982541|C...|W 258
|....|TE0365|. 2|88/ADJUSTED|N482357|W0982625|C...|X 258
|....|TE0362|. 2|88/ADJUSTED|N482212|W0982357|C...|U 258
|....|TE0360|. 2|88/ADJUSTED|N482116|W0982329|C...|Q 55
|....|TE0361|. 2|88/ADJUSTED|N482121|W0982334|B...|T 258
|....|TE0357|. 2|88/ADJUSTED|N481932|W0982247|C...|P 55
|....|TE0358|. 2|88/ADJUSTED|N481932|W0982247|C...|R 258
|....|TE0359|. 2|88/ADJUSTED|N482022|W0982309|C...|S 258
|....|TE0355|. 2|88/ADJUSTED|N481811|W0982209|C...|N 55
|....|TE0354|. 2|88/ADJUSTED|N481809|W0982208|C...|P 258
|....|TE0356|. 2|88/ADJUSTED|N481838|W0982221|C...|Q 258
|....|TE0352|. 2|88/ADJUSTED|N481655|W0982136|C...|M 258

|....|TE0351|. 2|88/ADJUSTED|N481655|W0982136|C...|M 55
|....|TE0348|. 2|88/ADJUSTED|N481418|W0982123|C...|K 55
|....|TE0349|. 2|88/ADJUSTED|N481511|W0982121|C...|L 258