

STB Tour of the Powder River Basin May 15 – May 18, 2006

Monday, May 15, 2006

Afternoon: Arrivals; check in at Wingate Hotel, 1801 Cliff Davis Dr., Gillette, WY
(307) 685-2700
6:30 p.m. Depart hotel for dinner
7:00 p.m. Dinner at Chop House

Tuesday, May 16, 2006

7:00 a.m. Depart hotel for mine tour
11:30 a.m. Lunch at mine
12:30 p.m. Depart mine for Bill, WY - Briefing with stops en route
3:00 p.m. Arrive and tour Union Pacific Rail Yard in Bill, WY
6:00 p.m. Arrive Hampton Inn & Suites, 301 W. Hwy. 26, Scottsbluff, NE (308) 635-5200
7:00 p.m. Dinner at Hampton Inn conference room

Wednesday, May 17, 2006

7:30 a.m. Depart Hampton Inn for South Morrill, NE
8:00 a.m. Board train at South Morrill, depart
9:00 a.m. *Glacier View Observation Car*
 9:00 a.m. Safety Briefing - Cameron Scott (UP)
 9:05 a.m. Anti-Trust Briefing - Lou Anne Rinn (UP)
 9:10 a.m. Welcome - Lance Fritz (UP) and Mark Kotter (BNSF)
 9:30 a.m. Presentations

- Joint Line Operations - Mark Kotter (BNSF)
- UP Coal Network Operations - Lance Fritz (UP)
- Powder River Basin Update - Steve Bobb (BNSF)
- Coal Network Capacity and Investment - Doug Glass (UP)

11:30 a.m. Lunch - *Overland Dining Car*
12:30 p.m. Tour Bailey Yard, North Platte, NE - Cameron Scott (UP)
2:45 p.m. *Glacier View Observation Car*

- UP's Triple Track and Engineering - Gene Reilly (UP)
- BNSF Coal Network Design & Maintenance of Way - Bob Boileau (BNSF)

5:30 p.m. Dinner - *Overland Dining Car*
7:30 p.m. Arrive in Omaha, NE (Durham Western Heritage Museum)
Transfer to hotels and airport
Hilton Garden Inn, 1005 Dodge Street, Omaha, NE (402) 341-4400
Doubletree Hotel, 1616 Dodge Street, Omaha, NE (402) 346-7600

Thursday, May 18, 2006

9:45 a.m. Depart hotels for Harriman Dispatching Center
10:00 a.m. Tour of the Harriman Dispatching Center, 850 Jones Street, Omaha, NE
11:45 a.m. Union Pacific Headquarters - Lunch
Afternoon: Depart Omaha